

25X1

Page Denied

Next 1 Page(s) In Document Denied

Exit onto concrete platform,
5 steps down to ground
level.

Fence with gate; gate
normally closed

25X1

CONFIDENTIAL INFORMATION REPORT

OPNAV FORM 3820-2 (C) (REV. 6-55)

CLASSIFICATION

FROM

REPORT NO.

DATE

CONFIDENTIAL

20 July 1959

25X1

Check point, room 6x12',
building has 2 floors

Pump exposed here, size unknown.

Water fittings. Hose has
to be led out across pier.

Floodlights

vessel

25X1

Most of fittings is within a
raised concrete "island". Walk-
way over this is approached by
concrete steps at either end.
Walkway to steel plate.

25X1

Long, continuous iron plate, flush
with pier level. [redacted]
petroleum lines run underneath this
because at frequent intervals a
portion of the plates would be
lifted by a worm checking some-
thing underneath. Extent of plating
unknown toward end of pier.

Pier length 1000'

30'

gate

Floodlights

small house

CLASSIFICATION

CONFIDENTIAL

From a U.S.S.R. chart of 1934

Scale 1:30,000

